



Commercial vehicle washing plant manufacturers

DESIGN • INSTALL • SERVICE

TGB

The Green Block

MSU

INFORMATION BOOKLET

Smith Bros. & Webb Limited
Britannia House
Arden Forest Estate
Alcester
Warwickshire
B49 6EX

Tel: +44 (0)1789 400096
Fax: +44 (0)1789 40 0231

User information and guidance

It is the responsibility of the operator to ensure that the following is adhered to with regards to the use of the MSU Equipment:

- All personnel are trained and authorised to enter the MSU
- All training is issued to personnel prior to working within the facility
- All personnel authorised to enter the MSU are issued with the correct PPE
- All emergency lighting is checked periodically in line with legislative requirements and records maintained
- Fire extinguishers are checked periodically in line with legislative requirements and records maintained
- Fire system is commissioned and signed off by relevant site safety personnel.
- IBC waste container is monitored and frequently changed when required
- MSU is left secure when not manned and any key equipment is isolated
- Drainage system is periodically flushed and sterilised with an approved biocide agent to reduce the risk of bacterial contamination and legionnaires.
- Any faults or issues that occur with regards to the equipment is to be reported to the service facilitator for supplier support
- Adequate signage is to be on display inside and surrounding the MSU warning others of any hazards and advising that CCTV is in operation
- First Aid facilities are available for all personnel using the MSU and contents regularly managed
- Adequate fire assembly points are to be allocated and communicated to all personnel and visitors
- Adequate spill kits are in place to suite the processes identified by the user
- Any equipment failures are to be reported to the TGB representative for support
- All equipment is used in accordance with the Original Equipment Manufacturers guidance as can be obtained from the same location as this information document
- Where specific Manufacturers information is not provided it is the responsibility of the equipment provider to supply such information and ensure operators have familiarised themselves with the contents.